



JON M. HUNTSMAN, JR.

Governor

GARY R. HERBERT

Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive DirectorJOHN R. BAZA  
Division Director**Inspection Report**Supervisor LR**Minerals Regulatory Program**

August 19, 2009

**Mine Name:** Lost Sheep Mine  
**Operator Name:** Michael Provstgaard

**Permit number:** S0230029  
**Inspection Date:** 05/14/2009  
 Follow up 06/17/2009  
**Time:** 1:30- 2:15 pm 05/14/2009  
**Time:** 11:00 am - 12:50 pm  
 06/17/2009

**Inspector(s):** Wayne Western & Brett Gregory**Other Participants:** None on 05/14/2009

Michael Provstgaard and Gail Provstgaard on 06/17/2009

**Mine Status:** ACT

**Weather:** No adverse conditions  
 affecting site visit.

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

The purpose of the visit was to conduct routine inspection of the mine. On the follow up visit the Division and the Permittee used a GPS to determine the disturbed area.

**Directions to Site:**

Easy access to site. For location, use Mine.tpo.

**Inspection Summary:**

The BLM sent the Permittee a letter stating that the notice had expired and that reclamation was required. In a phone call between Mr. Provstgaard and Wayne Western on May 18, 2009, the Permittee stated that things got straighten out with the BLM. The Permittee also disputed the area that is under the permit, less than 1 acre.

**Conclusions and Recommendations:**

The Permittee is in compliance.

Inspector's Signature

 8/19/2009

whw

cc: Michael Provstgaard

Jerry Mansfield, BLM

Permittee, PROVSTGAARD, MICHAEL S

Attachment: Map & Photos



Post law stockpile



Post law disturbed road cut



Post law structures



Pre law abandoned truck